



Modifications :

**ISSUE II**  
 MODIFIED. 12.9.55.

**ISSUE III**  
 CIRCUIT WAS  
 INCORRECTLY DRAWN  
 4.1.56.

**ISSUE IV**  
 FEED BACK LINE  
 1K WAS 4.7K.  
 150pf WAS 100pf  
 1ST 1/2 ECC 81  
 4.7K WAS 10K.  
 4.6.56.

TOLERANCES:

Unless otherwise stated:  
 .64" on fractional dims.  
 .005 on 3 place decimal dims.  
 The above do not apply to drilled  
 holes; diam. of wire or thickness of  
 sheet.

Screw Threads  
 B.S.W., B.S.F. & B.S.P. to spec. B.S.  
 84 1940 B.A. to spec. B.S. 93 1919  
 & C.F. (M.E.J. 652). Non Std. Threads to  
 B.S. 84 1940 Mod. Fit.

All specifications to latest issue  
 Machined diameters to be concentric  
 to within .004 T.C.R. Holes displaced  
 on a part circle to be within .001  
 true position.

**IMPORTANT**

THE CONTENTS INFORMATION AND COPYRIGHT OF  
 THIS DOCUMENT ARE THE SOLE PROPERTY OF  
 TANNOY LTD. AND MUST NOT BE USED,  
 PUBLISHED, APPLIED OR COPIED WITHOUT THE  
 EXPRESS KNOWLEDGE AND PERMISSION OF THE OWNERS



Drawn:	Date:	Material:
Traced <i>AS</i>	Date 21.7.55.	
Checked:	Date:	

WEST NORWOOD  
 LONDON  
 ENGLAND

Scale:  
 Finish:

Used on:

**HIGH QUALITY 20 WATT AMPLIFIER.**  
 TYPES HF/100/20L HF/200/20L

Drawing No. **C 16312**